

# Firmware Update

Changelog



# Firmware Update

## Changelog

---

### **BCN3D EMBEDDED OS (v1.5.0):**

#### **Fixed**

- Fixed reporting of some auto calibration errors.
- Fixed mesh mapping inconsistencies.
- Fixed head colliding in some dual / mirror prints.
- Fixed maintenance dialog that couldn't be closed.
- Improvements in auto calibration algorithm when finding the hole.
- Avoid motor lock after hotend change.
- Allow temperature changes by 1 degree from the touch screen.
- Improved several translation strings.

#### **Added**

- Local network access to the printer via web app on the printer's IP address.
- Restore settings.

#### **Changed**

- Updated SigmaSBC version to v0.22.2.
- Updated Marlin FW version to v0.17.6.